



CARGO - C113881 - Alternador para BMW serie 3 E46

ROVER YLE500170; BMW 7 789 980; BMW 12 31 7 797 660; BMW 7 789 983; BMW 7 797 660; BMW 12 31 7 789 980; BMW 12 31 7 789 983; ELSTOCK 28-5508; PowerMax 89212973; ARTEC 59212973; PowerMax 9212973; LUCAS

BMW 3 Compact (E46) [03/2001 a 02/2005] 318 td 115cv 85kw M47 D20 (204D4) Recambio...
BMW 3 Compact (E46) [03/2001 a 02/2005] 320 td 150cv 110kw M47 D20 (204D4) Recambio...
BMW 3 Coupé (E46) [12/1998 a 07/2006] 320 Cd 150cv 110kw M47 D20 (204D4) Recambio...
BMW 3 Coupé (E46) [12/1998 a 07/2006] 330 Cd 204cv 150kw M57 D30 (306D2) Recambio...
BMW 3 Descapotable (E46) [04/2000 a 12/2007] 320 Cd 150cv 110kw M47 D20 (204D4) Recambio...
BMW 3 Descapotable (E46) [04/2000 a 12/2007] 330 Cd 204cv 150kw M57 D30 (306D2) Recambio...
BMW 3 (E46) [12/1997 a 05/2005] 318 d 116cv 85kw M47 D20 (204D4) Recambio...
BMW 3 (E46) [12/1997 a 05/2005] 320 d 150cv 110kw M47 D20 (204D4) Recambio...
BMW 3 (E46) [12/1997 a 05/2005] 330 d 204cv 150kw M57 D30 (306D2) Recambio...
BMW 3 (E46) [12/1997 a 05/2005] 330 xd 204cv 150kw M57 D30 (306D2) Recambio...
BMW 3 Touring (E46) [06/1999 a 07/2005] 318 d 116cv 85kw M47 D20 (204D4) Recambio...
BMW 3 Touring (E46) [06/1999 a 07/2005] 320 d 150cv 110kw M47 D20 (204D4) Recambio...
BMW 3 Touring (E46) [06/1999 a 07/2005] 330 d 204cv 150kw M57 D30 (306D2) Recambio...
BMW 3 Touring (E46) [06/1999 a 07/2005] 330 xd 204cv 150kw M57 D30 (306D2) Recambio...
BMW X3 (E83) [01/2003 a 12/2011] 2.0 d 150cv 110kw M47 D20 (204D4) Recambio...
BMW X3 (E83) [01/2003 a 12/2011] 3.0 d 204cv 150kw M57 D30 (306D2) Recambio...
BMW X5 (E53) [01/2000 a 12/2006] 3.0 d 218cv 160kw M57 D30 (306D2) Recambio...
LAND ROVER FREELANDER I (L314) [02/1998 a 10/2006] 2.0 Td4 4x4 109cv 80kw 204D3 Recambio...
LAND ROVER FREELANDER I (L314) [02/1998 a 10/2006] 2.0 Td4 4x4 112cv 82kw M 47




Para consultar precios y condiciones les recomendamos que acceda a nuestra tienda:

<http://www.recambiodirecto.com>

Recambio Directo - Francisco Gómez Caro

Av. de la Paz 18 - 14700 Palma del Río - Córdoba - España

Tel +34 957 643 322 - 34 957 644 447 - 619 273 575



Whatsapp: 659 813 960 - email: info@recambiodirecto.com